



Not Just Toners & Drums
Everything for Copiers

The Instruction of Assembling Drums for AF1035 Series

After assembling the drum, you are supposed to check the voltage of charge roller (SP2-001-1), to perform the ID Sensor-Initialization (SP3-001-2) and the Developer Initialization(SP2-805).

To enter the service mode, please press the following buttons successively: the yellow clear-all button, 1-0-7 (by the numeric pad) and finally hold down the clear button at least for 3 seconds.

You have to get items done as follows ordinally.

1. Make sure that the charge roller voltage supply the standard value (enter SP2-001-001)
2. Do the ID Sensor Initial Setting procedure (enter SP3-001-002)
3. Do SP2-805 (developer initialization)

This instruction is for use in below copiers.

Aficio 1035/1045

Aficio 2035/2045/3035/3045

Aficio 340/350/355/450/455

Aficio MP3500/4500

Aficio MP4000/5000

Aficio MP4001/4002/5001/5002

Printech Imaging Co., Limited

Phone: +86 186 6695 7372
Web.: www.printeching.com
Email: sales@printeching.com